REVENUE SECRETARIAT

OFFICE OF THE ASSISTANT ENGINEER, NO. I SUB-DIVISION, TUMKUR.

Notification dated 1st July 1954.

Under Section 29(1) of Mysore Irrigation Act as amended and VII of 1938 and VII of 1952, the following list of Irrigation Work with detailed particulars involving levy of water rate and contribution are hereby notified for information of the public concerned. Any representation on the subject from any of the concerned ryots may be prefered before the undersigned in his office during office hours within 35 days from the last date of publication in the *Mysore Gazette*, after which no representation will be entertained.

Statement showing the works under various stages taken up under 18-A, Irrn. "C" Restoration of minor tanks by desilting and 18-A. Irrigation Extension and Improvements, etc., (G.M.F. Scheme) in Tumkur and Koratagere Taluk.

Sl. No.	Name of Village	Name of Tank	Nature of work	Sl. No.	Rgester No.	Amount of Estimate in case of works under progress	Amount of Contribution	Atchkat Existing A.	Atchkat Fresh A. G.	Water rate	Remarks
1	Bellavi ...	Bellavi Tank ...	Effecting improvements to Bellavi Tank.	365	311	260	70	47	...	Proportionate Extra Water Rate is levied in addition to Water Rate already existing subject to the Maximum limit of Rs. 9 per acre inclusing the existing assessment.	Work completed.
2	Aslipura ...	Aslipura Tank..	Improvements to Sluice of Aslipura Tank.	369	307	1,357	339	132	...		do
3	Neralapura ...	Neralapura Tank.	Urgent Repairs and Improvements to Neralapura Tank.	577	111	3,500	900	67	...		do
4	Kembalalu ...	Amanikere ...	Improving feeder by Providing Silt dam to Kembalalu Amanikere from Kodimundinahalli.	608	266 158	2,350	590	792	...		do
5	Do ...	Do ...	Constructing Masonry Relieving weir to Kembalalu Amanikere ...	608	266 158	1,316	329	792	...		do
6	Rampura, Venkatapura.	...	Improving flood bank of Suvernamukhi near Rampura Venkatapura.	...	...	1,934	484	200	...		do
7	Kyatasandra ...	Gundlammana Katte.	Providing pipe Sluice in place of damaged one of Gundlammana Katte.	451	203	1,572	393	15	...		do
8	Devalapura ...	Devalapura Tank.	Providing C. I. pipe Sluice in place of leaky Sluice of Devalapura Tank.	397	196	1,421	355	159	...		do
9	Devarayanadurga State Forest.	Naikana Kere...	Urgent repairs to leaky Sluice of Naikanakere.	257	...	3,362	840	19	...		do
10	Gulur ...	Amanikere ...	Improvements to Gulur feeder channel near Manchagondanahalli.	488	69	544	136	488	...		do
11	Do ...	Do ...	Improvements to feeder halla of Gulur Tank near Byrasandra.	488	69	4,000	1,000	488	...		do
12	Do ...	Do ...	Improvements to Gulur Tank and Channels.	488	69	4,000	1,000	488	..		do
13	Karikere ...	Karikere Tank	E. W to weak pertion of Bund of Karikere Tank.	403	236	605	150	69	...		do
14	Pemmanahalli ...	Dasanayakana Kere.	Improvements to waste weir of Pemmanahalli Dasanayakanakere.	463	156	1,600	400	28	...		do
14a	Do ...	...	Turfing the Bund of Pemmanahalli Dasanayakanakere.	463	156	1,100	275	28	...		do
15	Saslu ...	Saslu Tank ...	Improvements to Sluice and weir and channel of Saslu Tank.	596	123	2,434	608	293	...		do
16	Hebbur ...	Amanikere ...	Urgent Improvements to left Slvice channel of Hebbur Amanikere.	618	192	1,100	275	1024	...		do
17	Sompur ...	Do ...	Constructing Sopanams, Improving Culvert and constructing pipe Sluice to Sompur Nala.	271	47	1,022	255	38	...		do
18	Gatlahalli ...	Gatlahalli Tank	Repairs to acqueduct and providing new Sluice and other urgent repairs to Gatlahalli Tank.	294	164	2,500	625	174	...		Work under progress
19	Aregujjanahalli ...	Tank ...	Protective works to bund of Aregujjanahalli Tank.	454	...	1,446	361	36—18	...		Work completed
20	Kerigagalahalli ...	Amanikere ...	Opening out a feeder channel to Kereyagalahalli Tank.	278	26	600	150	21	...		do
21	Mudigere ...	Mudigere Tank	Urgent repairs to Mudigere Tank	375	308	500	125	131	...		do
22	Do ...	Do ...	Turfing the bund of Mudigere Tank.	375	308	550	137	13	...		do
23	Maraloor ...	Alasettykere ...	Constructing C. S. pipe Sluice to Alasettykere Tank in place of damaged one.	443	14	1,870	467	351	...		do
24	Kambathanahalli	Tank ...	Strengthening the Bund of Kambathanahalli Tank.	493	22	4,000	1,000	101	...		Work under progress
25	Mallasandra ...	Amanikere ...	Improvements to Tank and channels of Mallasandra.	497	21	2,800	700	788	...		do
26	Settyhalla ...	Kengatte ...	Urgent Improvements to Sluice of Settyhalli Kengatte.	....	... 134	1,068	267	80	...		Completed
27	Thondigere ...	Tank ...	Providing C. I. pipe Slice to Thondikere Tank.	335	—— 242	1,000	250	22	...		Work completed
28	Bittanakurke ...	Do ...	Desilting Bittanakurke Tank ...	396	202	2,300	575	65	....		do
29	Nelhal ...	Do ...	Do Nelhal Tank ...	131	249	1,500	375	22	...		do
30	Devalapura ...	Do ...	Do Devalapura Tank ...	397	196	2,000	500	159	...		do
	Do ...	Do ...	Turfing the Bund of Devalapura Tank.	397	196	1,630	407	159	...		do
31	Hiregundagal ...	Do ...	Desilting Hiregundagal Tank ...	410	245	2,200	550	167	...		do
32	Do ...	Do ...	Turfing the Bund of Hiregundagal Tank.	410	245	1,200	300	167	...		do
33	Chickgundagal ...	Sowthikatte ...	Desilting Chickgundagal Sowthikatte.	407	250	1,150	287	106	...		do
34	Hebbaka ...	Amanikere ...	Gravelling the Bund of Hebbaka Tank.	419	19	2,000	500	334	...		do
35	Hanchihalli ...	Tank ...	Desilting of Hanchihalli Tank ...	414	288	1,200	300	69	...		do
36	Kempandodderi ...	Do ...	Do Kempanadodderi Tank	381	194	2,050	510	61	...		do
37	Kotnahalli ...	Goravanakatte	Turfing the Bund of Kothihalli Goravanakatte.	427	341	350	90	18	...		do
38	Banorihalli ...	Tank ...	Confining halla flowing in to Bandrihalli Tank.	...	...	1,000	250	...	...		do
39	Bommaladevipura	Doddakere ...	Strengthening bund of Bommaladevipura Tank.	220	45	3,000	750	83	...		do
40	Thogarighatta ...	Do ...	Restoration by desilting Thogarighatta Tank.	221	43	3,000	750	117	...		do
41	Amani Hosakere	Amanikere ...	Constructing Gradewall to Jolly halla pick-up.	445	25	980	245	359	...		do
42	Kanchihalli ...	Tank ...	Earth work to Bund of Kanchihalli Tank, Kora Hobli.	...	...	666	166	...	...		do

2786

T. V. RAMAIYA, *Asst. Engineer.*